# TORO PVB/ 80-0550/ 80-0560

### SIZE

80-0550 - 3/4" 80-0560 - 1"

## **DESCRIPTION**

This is a pressure vacuum breaker assembly. Production began approximately 1977 and discontinued around 2020. The 3/4" was discontinued approximately in 2001 and the 1" was discontinued a couple years later. It is a celcon plastic bodied unit with ball valve shutoffs built into the assemblies body. The check seat is cast in the body and is not replaceable. There is spring tension from the check spring when the bonnet is unscrewed. Internal hardware parts are mostly made of plastic. The original model designation was PVB; it later adopted the separate model number for each size.

### **BASIC REPAIR KIT**

Repair kit contains check assembly, check spring, float, float spring, and cover O-ring

<u>SIZE</u>	KIT NO
3/4"	900-44 *◆
1"	900-44 *◆

# **IMPORTANT FEATURES**

- ~Plastic body
- ~Integral ball valve
- ~Check seat cast in the body
- ~Check spring is not contained when bonnet is removed



